

## INSTALLATION INSTRUCTION

### SENSOR ON/OFF VIA MOVING HAND (VT-8025)

#### TECHNICAL DATA:

|                      |                                                    |
|----------------------|----------------------------------------------------|
| Power Sourcing:      | 220-240V/AC                                        |
| Power Frequency:     | 50/60Hz                                            |
| Rated Current:       | 5A                                                 |
| Rated Load:          | 500W (Traditional Lighting)<br>200W (LED Lighting) |
| Detection Distance:  | 5-6cm                                              |
| Working Temperature: | -20~+50°C                                          |



**2 YEARS  
WARRANTY**

#### INTRODUCTION & WARRANTY

Thank you for selecting and buying V-TAC product. V-TAC will serve you the best. Please read these instructions carefully before starting the installation and keep this manual handy for future reference. If you have any another query, please contact our dealer or local vendor from whom you have purchased the product. They are trained and ready to serve you at the best.

The warranty is valid for 2 years from the date of purchase. The warranty does not apply to damage caused by incorrect installation or abnormal wear and tear. The company gives no warranty against damage to any surface due to incorrect removal and installation of the product. This product is warranted for manufacturing defects only.

This is a Short Distance IR Sensor. Its ON or OFF is controlled by hand movements. When you move your hands towards the IR sensor, it gets detection and turn on the light. The light will be switched off until the IR sensor detects another movement by hands.

#### **(HU)** BEVEZETÉS ÉS GARANCIA



Köszönjük, hogy választotta és megvásárolta a V-TAC terméket. V-TAC nyújtja Önnek a legjobb szolgáltatást. Kérjük, a szerelés előtt figyelmesen olvassa el ezeket az utasításokat és óvja ezt a kézikönyvet későbbi használatra. Ha további kérdései vannak, kérjük, forduljon forgalmazójához vagy helyi eladójához, akitől megvásárolta a terméket. Ők képzettek és készek a legjobb szolgálatra.

A jótállás a vásárlás napjától számítva 2 évig érvényes. A garancia nem vonatkozik a helytelen szerelés vagy az abnormális kopás okozta károkra. A cég nem vállal semmilyen garanciát a felület károsodásáért, a termék helytelen eltávolításáért és szereléséért. Ez a termék garanciája csak a gyártási hibákra vonatkozik.

## INSTALLATION INSTRUCTION:

- Switch off the power.
- Install the product on the wall with two enclosed inflated screws.
- Connecting the power and the load to sensor as the connection-wire diagram.
- Switch on the power and test it

#### CONNECTION-WIRE DIAGRAM



## TEST:

- Switch on the power.
- When you move your hands towards the IR sensor, it gets detection and turn on the light. The light will be switched off until the IR sensor detects another movement by hands.

**NOTE:** In front of the detection window there shouldn't be hinder or unrest objects affecting detection.

#### WARNING

1. Please make sure to turn off the power before starting the installation.
2. Must be installed by professional electrician.



This marking indicates that this product should not be disposed of with other household wastes.



Caution, risk of electric shock.

#### FELSZERELÉSI ÚTMUTATÓ

- Kapcsolja ki a tápellátást.
- Szerelje fel a terméket a falra a csomagban lévő két dűbel segítségével.
- Csatlakoztassa a tápellátást és a terhelést az érzékelőhöz az áramkörü rajz szerint..
- Kapcsolja be a készüléket és tesztelje azt.